


**HISTORIC COASTAL PHOTOGRAPH BY RICHARD K. HALE**

**PHOTO 179.** *South Lake Worth Inlet, Florida.* Beach erosion south of the inlet was already a problem in the 1930's (note the large indentation in the shoreline to the right of the photo center). (Photo: Photo Archives at the Coastal Engineering Research Center, US Army Engineer Waterways Experiment Station, Vicksburg, Mississippi. 23 April 1938).