
COASTAL PHOTOGRAPH BY ANGUS JACKSON




PHOTO 106. Trailing suction hopper dredge W.H. Resolution bottom dumping 1.5×10^6 m³ of sand dredged from offshore (23 m depth) in 6 to 10 m of water off the Kirra and Bilinga Beaches, Gold Coast, Australia, where some 2 Km of beach has been lost and the foreshore is presently protected by a boulder wall. The cost of the works was A\$2.5 $\times 10^6$. (Photo: Angus Jackson, Supervising Engineer—Special Projects, Gold Coast City Council, Gold Coast, Queensland, Australia.)