


---

**COASTAL PHOTOGRAPH BY H. J. WALKER**

---



**PHOTO 167.** The chemical decomposition (rusting) of metal seawall piling on the Texas coast. Note the new cement seawall behind the decaying metal one. (Photo: Jess Walker, Department of Geography and Anthropology, Louisiana State University, Baton Rouge, Louisiana).