

---

**COASTAL PHOTOGRAPH BY PER BRUUN**

---



**PHOTO 170.** *Beach spoiling on the North Sea coast.* Pumping over the bow is a practical method of sand emplacement for beach renourishment projects in many parts of northern Europe. (Photo: Per Bruun, 34 Baynard Cove Road, Hilton Head, South Carolina. May 1988).