



Cape May, New Jersey. Jetties at Coldspring Inlet in the upper left of the photo have caused an offset in the shoreline. A groin field protects the shoreline of the City of Cape May in the center of the photo. (October 29, 1991 by Fred E. Camfield, Wave Dynamics Division, Coastal Engineering Research Center, US Army Engineer Waterways Experiment Station, Vicksburg, Mississippi).